Chains

ryegrass, tule and a mixture of native meadow grasses in the bottom land.

Dependent resurvey of the Eighth Standard Parallel North from the closing corner of Ranges 24 and 25 East to the standard corner of secs. 33 and 34, Range 25 East.

Reestablishment of the survey executed by G. W. Garside, Deputy Surveyor, in 1873.

The original survey of the Eighth Standard Parallel North along the N. bdy. of T. 40 N., R. 25 E. was initiated at the closing corner of Ranges 24 and 25 East.

From the closing corner of T. 40 N., Rs. 24 and 25 E.

N. 89° 09' E., along N. bdy. sec. 6.

Ascend 140 ft. over steep W. slope.

Point for the standard corner of T. 41 N., R. 24 and 25 E. at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 3 ins. diam., over a cross mkd. on surface rock, and in a mound of stone to top, with brass cap mkd.

SC THIN R2LLE | R25E S36 | S31

Land, mountainous.
Soil, rocky; 3rd rate.
Timber, none.
Undergrowth, sagebrush.
Grazing, fairly good.

N. 89° 09' E., along the S. bdy. of sec. 31.

Ascend 60 ft. over steep W. slope.

2.50 Ascend 40 ft. over gradual W. slope.

10.00 Across top of broad spur, projects S.

22.00 Descend 40 ft. over general E. slope.

The standard  $\frac{1}{4}$  sec. cor. of sec. 31, marked by the original monument, a lava stone, 3x12x12 ins., mkd.  $\frac{1}{4}$  on N. face, loosely set in the ground at the S. side of an old mound of stone.

At the corner point

Set an iron post, 3 ft. long, 1 in. diam., 14 ins. in the ground to underlying rock, with brass cap mkd.