

Dependent Resurvey of the Subdivision of
T. 35 N., R. 62 E.

Chains
39.95

The original $\frac{1}{4}$ sec. cor., a juniper post, $1\frac{1}{2}$ ins. diam., broken in pieces totaling 32 ins. in length, one piece mkd. $\frac{1}{4}$ on one face, fallen on a low mound of earth.

At point for corner

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, with a quartzite stone, 8x6x2 ins., mkd. with a cross (X), and the pieces of the original post deposited at the base, for $\frac{1}{4}$ sec. cor., with brass cap mkd.

$\frac{1}{4}$
S3 | S2
1943

No suitable accessory.

Thence

N. 3° 41' E., bet. secs. 2 and 3. (N. $\frac{1}{2}$ mile.)

Over nearly level land.

34.90 Unimproved road, bears S. 85° W. and N. 85° E.

41.97 The original closing cor. of secs. 2 and 3, a cottonwood post, 3 ins. diam., 24 ins. above ground, squared on three faces, with faint scribe marks, firmly set at the center of a low mound of earth bet. faint outlines of pits to the E. and W.

42.22 Intersect the Seventh Standard Parallel North.

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, with charcoal deposited at the base, for closing cor. of secs. 2 and 3, with brass cap mkd.

T36N R62E
S 34
T35N R62E
S3 | S2
CC
1943

No suitable accessory.

From the closing corner, the standard cor. of secs. 34 and 35, an iron post, 3 ins. diam., set, mkd. and witnessed as described in the official record, bears S. 89° 40' E., 20.58 chs. dist.; and the standard $\frac{1}{4}$ sec. cor. of sec. 34, an iron post, 1 in. diam., set, mkd. and witnessed as described in the official record, bears N. 89° 40' W., 19.49 chs. dist.

Land, nearly level.

Soil, sandy clay loam; 3rd rate.

No timber; undergrowth, sagebrush.

Grazing, fair..

From the cor. of secs. 3, 4, 33 and 34, on the S. bdy. of the township, an iron post, 2 ins. diam., described in the field notes of the resurvey of T. 34 N., R. 62 E., executed under this same group.