

DEPENDENT RESURVEY OF PORTION OF THE NORTH BDY. OF T. 18 N., R. 19 E.

Chains

S 34

 $\frac{1}{4}$ S 3
1944

This corner is situated on rocky W. slope at S. side of prominent basalt outcrop.

Ascend 30 ft.

46.10 Rocky crest of mesa near north end; extends W. and SE.; desc. broken, rocky NE. slope 300 ft.

78.55 The original cor. of secs. 2, 3, 34 and 35 which is a granite rock, 15x8x7 ins., mkd. 2 notches on E. and 4 on W. edges, firmly set in an old scattered mound of stones.

At point for corner, in center of mound,

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, with the original stone deposited at the base, for cor. of secs. 2, 3, 34 and 35, with brass cap mkd.

T19N R19E

S 34 | S 35

S 3 | S 2

T18N

1943

raise a mound

of stone, 5 ft. base, around post.

From this cor., the original cor. of secs. 1, 2, 35 and 36, Ts. 18 and 19 N., R. 19 E., bears N.89°21'E., 79.51 chs. dist.; a basalt rock, 19x10x8 ins., mkd. 1 groove on E. and 5 grooves on W. faces, firmly set in an old imbedded mound of stones.

At point for cor.

Set an iron post, 3 ft. long, 2 ins. diam., 16 ins. in the ground and in mound of stone 6 ft. base, the original stone deposited at the base, for cor. of secs. 1, 2, 35 and 36, with brass cap mkd.

T19N R19E

S 35 | S 36

S 2 | S 1

T18N

1944

Land, hilly and mountainous.

Soil, coarse, shallow, rocky, 3rd rate.

Undergrowth, sagebrush, briar, willow, choke cherry.

Timber; scattering yellow pine and mahogany in W. $\frac{1}{2}$ mile.

Grazing; fair.

DEPENDENT RESURVEY OF A PORTION OF THE EAST BDY. OF T. 18N., R.19 E.

Reestablishment of survey executed by J. S. Lawson, Deputy Surveyor, in 1861.

From the cor. of Ts. 17 and 18 N., Rs. 19 and 20 E.,

N. 0° 36' E., bet. secs. 31 and 36 (South half mile.)

Over broken mountainous land thru very dense tall undergrowth. Desc. along gentle rocky W. slope.

9.40 Slope changes to abrupt rocky NW. slope., desc. 360 ft.