

## Dependent Resurvey of the South Boundary of T. 21 S., R. 62 E.

## Chains

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for cor. of secs. 5, 6, 31, and 32, with brass cap mkd.

T 21 S R 62 E
S 31   S 32
S 6   S 5
T 22 S
1943

raise a mound

of stone, 2½ ft. base, 1½ ft. high, W. of cor.

Land, level tableland.

Soil, rocky and gravelly, 3d rate.

No timber.

Undergrowth, creosote and other desert brush.

Poor grazing land.

N. 87° 15' W., bet. secs. 6 and 31.

Over top of tableland covered with lava rock, through short undergrowth.

12.10 Unimproved road, bears N. and S.

13.50 Wash, 25 lks. wide, 3 ft. deep, drains N.

16.20 Unimproved road, bears N. 20° W. and S. 20° E.

26.90 Wash, 20 lks. wide, 7 ft. deep, drains N. 10° E.

42.22 Proportionate point, near NE. cor. of fence bearing westerly and southerly,

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for ¼ sec. cor., with brass cap mkd.

S 31
¼
S 6
1943

from which

A mesquite, 3 ins. diam., bears N. 35° W., 50 lks. dist., mkd. ¼ S 31 BT.

A mesquite, 10 ins. diam., bears S. 18° E., 38 lks. dist., mkd. ¼ S 6 BT.

72.80 Unimproved road, bears N. and S.

82.76 The cor. of Tps. 21 and 22 S., Rs. 61 and 62 E., a 3 inch iron post, set, mkd., and witnessed as described in the field notes of the resurvey of T. 22 S., R. 62 E., of this group.

Land, nearly level.

Soil, sandy, 3d rate.

No timber.

Undergrowth, creosote and mesquite.

Fair grazing land.

Dependent Resurvey of the West Boundary of T. 21 S., R. 62 E.

Reestablishment of surveys executed by Brunt and Proctor,  
Deputy Surveyors, in 1881.

From the cor. of Tps. 21 and 22 S., Rs. 61 and 62 E.,