


Dependent Resurvey of the West Boundary of T. 21 S., R. 62 E.

Chains

- 18.80 Graded road, bears NE. and SW., also mouth of small side wash, drains N. 10° W.
- 22.00 Main channel of wash, 100 lks. wide, 1 ft. deep, in flood plain, 10 chs. wide, drains NE.
- 30.20 The W. bank of flood plain, bears NE. and SW.
- 40.57 Proportionate point.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.




from which

A mesquite, 12 ins. diam., bears N. 49° 15' W., 2.25 chs. dist., mkd. $\frac{1}{4}$ S 12 BT.

No other bearing tree available.

- 50.20 The NW. bank of flood plain, bears NE. and SW.
- 50.80 Unimproved road, bears NE. and SW., on low spur, slopes NE.
- 56.20 Small spur, slopes NE.
- 63.80 Unimproved road, bears E. and W.
- 74.80 Unimproved road, bears E. and W.
- 81.14 Proportionate point.

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for cor. of secs. 1, 6, 7, and 12, with brass cap mkd.



raise a mound
of stone, 2 $\frac{1}{2}$ ft. base, 1 $\frac{1}{2}$ ft. high, W. of cor.

From the cor:

U. S. Coast and Geodetic Survey bench mark No. T-51, a brass tablet set in concrete, bears S. 43° 49' E., 71.14 chs. dist. and U. S. Geological Survey bench mark, bears N. 25° 24' W. Bench mark on E. side of highway.

Land, rolling.
Soil, sandy and gravelly, 4th rate.
No timber.
Undergrowth, mesquite and desert brush.
Poor grazing land.

N. 0° 03' E., bet. secs. 1 and 6.

Over rolling land, through short undergrowth.