

Dependent Resurvey of the 5th Standard Parallel South,
through Range 53 East.

Chains

in the vicinity for many years, it and similar monuments were set by Engineer Wallace Brough at the time of his survey of the boundaries of the Pahrump Ranch, in 1915. It is accepted as the best evidence of the position of the original corner.

At the corner point

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, with brass cap mkd.

SC
T20S R53E
S31 S32

1948

Reset the juniper post alongside the iron post and raise a flat mound of stone, 3 ft. diam., around the post.

Land, level.

Soil, clay.

Undergrowth; shadscale, with mesquite along the wash area.

N. 89° 53' W., along the S. bdy. of sec. 31.

Over level desert, through scattered shadscale.

40.32

The standard $\frac{1}{4}$ sec. cor. of sec. 31, monumented with a squared mesquite post, 2x2 ins., 1 ft. above ground, mkd. $\frac{1}{4}$ on the N. face, other scribe marks illegible.

At the corner point

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, with brass cap mkd.

SC
 $\frac{1}{4}$ S 31

1948

dig pits, 18x18x12 ins., E. and W. of post, 3 ft. dist., and reset wood post alongside the iron post.

S. 89° 51' W., beginning new measurement.

40.56

The standard cor. of Ts. 20 S., Rs. 52-53 E., monumented with a squared mesquite post, 2x2x8 ins. above a mound of earth and brush, 4 ft. diam., 1 $\frac{1}{2}$ ft. high, mkd. SC on N. face, with 6 notches in the NE., SE., SW., NW., edges.

At the corner point

Set an iron post, 3 ft. long, 3 ins. diam., 30 ins. in the ground, with brass cap mkd.

SC
T20S
R52E R53E
S36 S31

1948