

## CHAINS

in a mound of stone and plainly mkd.  $\frac{1}{4}$  on the E. face.

At the corner point.

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 10 ins. in the ground to bedrock and in a mound of stone,  $4\frac{1}{2}$  ft. base to cap, with brass cap mkd.

T42N R39E  
 $\frac{1}{4}$   
 | S 9  
 1962

Bury the original corner stone alongside the iron post.

From this corner the E.  $\frac{1}{4}$  sec. corner of sec. 8, monumented with an iron post, 1 ins. in diam., set, mkd., and witnessed as described in the official record, bears S  $0^{\circ} 03' E.$ , 4.13 chs. dist.

The W.  $\frac{1}{4}$  sec. cor. of sec. 4, in fence, bearing N. and S., monumented with a sandstone, 12x10x8 ins., firmly set in a mound of stone and plainly mkd.  $\frac{1}{4}$  on the E. face.

At the corner point.

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 18 ins. in the ground to bedrock and in a mound of stone,  $4\frac{1}{2}$  ft. base, to cap, with brass cap mkd.

T42N R39E  
 $\frac{1}{4}$   
 | S 4  
 1962

Bury the original corner stone alongside the iron post.

From this cor. the E.  $\frac{1}{4}$  sec. cor. of sec. 5, monumented with an iron post, 1 ins. in diam., set, mkd., and witnessed as described in the official record, bears S.  $0^{\circ} 10' W.$ , 4.13 chs. dist.

## GENERAL DESCRIPTION

The land surveyed within this township is nearly level to rolling land located in Paradise Valley. The soil varies from sandy clay to sandy clay and rocky. The area drains southeast into the valley, thence southerly. There is no timber.

Principal users of the area are cattlemen and a considerable amount of hay is grown on the private lands. Access into the township is provided by State Highway 8B, which bears northerly through the township and other improved and trail roads.

No mineral formations of consequence were noted during the survey.