

CHAINS

T18S R66E

$\frac{1}{2}$
S 3 | S 2
1963

Raise a mound of stone, $3\frac{1}{2}$ ft. base, $2\frac{1}{2}$ ft. high, W. of cor.

66.60 Nevada State Highway 40, bears N. 40° E. and S. 40° W.

79.70 The cor. of secs. 2, 3, 34 and 35, on the N. bdy. of the Tp., which is monumented with an iron post, $2\frac{1}{2}$ ins. diam. set, mkd. and witnessed as described in the official record.

Land, broken and rocky.
Soil, sandy.
Undergrowth, scattered cactus and creosote bush.

From the cor. of secs. 2, 3, and 11.

N. $89^\circ 58'$ W., along the S. bdy. of sec. 3.

Asc. 190 ft. along broken N. slope.

24.10 Top of spur projects N., desc. 400 ft. down WNW slope.

40.00 Point for the S. $\frac{1}{4}$ sec. cor. of secs. 3

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 5 ins. in the ground to bedrock and in a mound of stone, 3 ft. base to top of cap, with brass cap mkd.

T18S R66E

$\frac{1}{2}$ S 3
1963

Raise a mound of stone, 4 ft. base, 3 ft. high, N. of cor.

Desc. 30 ft. down W. slope.

42.10 Wash, 20 lks. wide, $1\frac{1}{2}$ ft. deep, drains N., asc. 210 ft. up E. slope.

63.50 Top of spur projects E. irregular, thence along broken rocky N. slope.

78.60 Top of spur projects E., desc. 30 ft. over SW. slope

80.00 Point for the cor. of secs. 3 and 4.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 5 ins. in the ground to bedrock and in a mound of stone, $3\frac{1}{2}$ ft. base to top of cap, with brass cap mkd.

T18S R66E

S 4 | S 3
1963

Land, broken and rocky.
Soil, sandy.
Undergrowth, scattered cactus and creosote bush.