

DEPENDENT RESURVEY OF THE E. BDY. OF T. 5 S., R. 60 E.

CHAINS

- 2.10 Spur, slopes W.; desc. 730 ft. over a steep, broken N. slope.
- 33.50 Ravine, drains W., enter rolling land; desc. gradual rolling N. slope.
- 39.85 Point for the $\frac{1}{4}$ sec. cor. of secs. 1 and 6, at proportionate distance; there is no remaining evidence of the original corner.
- Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 10 ins. in the ground to bedrock and in a mound of stone to top, 4 ft. base, with brass cap mkd.
- T5S
R60E R61E
 $\frac{1}{4}$
S 1 | S 6
1964
- Desc. 80 ft. over a rolling N. slope.
- 57.60 Wash, 25 lks. wide, 3 ft. deep, drains W.; asc. 20 ft. over a S. slope.
- 60.80 U. S. Highway No. 93, bears NE. and SW. on curve; asc. 90 ft. over a S. slope.
- 62.00 Telephone line, parallel to Highway.
- 67.25 Intersect the First Standard Parallel South.
- Point for the closing cor. of T. 5 S., Rs. 60 and 61 E., at proportionate distance; there is no remaining evidence of the original corner.
- Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 6 ins. in the ground to bedrock and in a mound of stone to top, 4 ft. base, with brass cap mkd.
- T4S R60E
S 36
S 1 | S 6
T5S T5S
R60E R61E
CC
1964
- From this corner, the standard corner of T. 4 S., Rs. 60 and 61 E. bears N. $89^{\circ} 33'$ E., 12.37 chs. dist.
- Land, broken, rolling.
Soil, clay, rocky.
Undergrowth, creosote brush, greasewood.

GENERAL DESCRIPTION

The land along lines surveyed vary from rolling to rough, broken hills. The soil is a sandy loam, gravel, clay and exposed granite. The vegetation consists of greasewood, creosote brush and sparse native grasses. There is no timber.