

DEPENDENT RESURVEY OF THE SUBDIVISIONAL LINES,
T. 1 N., R. 53 E.

CHAINS	
70.40	Nevada State Highway 25, bears S. 17° E. and N. 17° W.
81.97	<p>The cor. of secs. 6 and 7, on the W. bdy. of the Tp.</p> <p>Land, nearly level. Soil, sandy clay and alkali. Undergrowth, shadscale and barren lake bed.</p>
40.33	<p>From the cor. of secs. 5, 6, 7 and 8.</p> <p>N. 1° 43' E., bet. secs. 5 and 6.</p> <p>Over nearly level dry lake bed.</p> <p>Point for the $\frac{1}{4}$ sec. cor. of secs. 5 and 6, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center;"> <p>T1N R53E</p> <p>$\frac{1}{4}$</p> <p>S 6 S 5</p> <p>1966</p> </div> <p>raise a mound of stone, 3 ft. base, 2 ft. high, W. of cor.</p>
80.55	<p>The cor. of secs. 5, 6, 31 and 32, on the N. bdy. of the Tp.</p> <p>Land, nearly level. Soil, sandy clay and alkali. Undergrowth, none.</p>
	<p style="text-align: center;">GENERAL DESCRIPTION</p> <p>The land within Township 1 North, Range 53 East, is nearly level to gently rolling. The elevation ranges from about 4,850 to 5,200 ft. above sea level. The soil varies from sandy gravel to sandy clay and alkali. The vegetation consists of shadscale, budsage and native grasses. There is a dry lake bed, which sets in sections 4 and 5, and parts of sections 3, 6, 7, 8, 9 and 10. There is no vegetation on the lake bed.</p> <p>There are four wells located in sections 3, 7, 27 and 31.</p> <p>State Highway Maintenance Station DIABLO is in section 32.</p> <p>No mineral formations of consequence were noted during the survey.</p> <p>Principal users of the area are cattlemen and access into the township is provided by State Highway 25, which enters the township in section 32 and leaves in section 6. Other access is provided by desert roads.</p>