

## DEPENDENT RESURVEY, SOUTH BOUNDARY, T. 34 N., R. 35 E.

## CHAINS

Reestablishment of the Survey Executed by  
W. Epler, U. S. Deputy Surveyor, in 1867

Beginning the resurvey at the cor. of Tps. 33 and 34 N.,  
Rs. 35 and 36 E., monumented with a squared wooden post,  
2x2x30 ins., dimly scribed and loosely set, with a small  
mound of stone to the S.

At the corner point

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 22 ins. in  
the ground, with brass cap mkd.

T34N			
R35E		R36E	
S	36	S	31
S	1	S	6
T33N			

1966

reset the wooden post and set a steel fence post, 7 ft.  
long,  $2\frac{1}{2}$  ft. in the ground, alongside the iron post.

N.  $89^{\circ} 53'$  W., bet. secs. 1 and 36.

Over rolling land, through medium undergrowth; desc. 110  
ft. over a W. slope.

- 9.40 Ravine, drains WSW.; desc. 50 ft. over a W. slope.
- 16.40 Same ravine, drains WNW.; desc. 120 ft. over a N. slope.
- 40.15 Point for the  $\frac{1}{4}$  sec. cor. of secs. 1 and 36, at pro-  
portionate distance; there is no remaining evidence of  
the original corner.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 22 ins. in  
the ground, with brass cap mkd.

T34N		R35E	
$\frac{1}{4}$	S 36		
	S 1		
T33N			

1966

set a steel fence post, 7 ft. long,  $2\frac{1}{2}$  ft. in the ground,  
alongside the iron post.

Desc. 30 ft. over a N. slope.

- 50.30 Slope changes to W.; desc. 100 ft. over a gradual W.  
slope.
- 78.10 Wash, 10 lks. wide, 2 ft. deep, drains NW.
- 80.30 The cor. of secs. 1, 2, 35 and 36, monumented with a  
squared wooden post, 3x3x16 ins., loosely set in a small  
mound of earth.