SURVEY OF A PORTION OF THE SUBDIVISIONAL LINES, T. 10 N., R. 27 E.

CHAINS

79.50

Intersect the W. bdy. of sec. 8.

Point for the closing cor. of secs. 7 and 18.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 22 ins. in the ground, with brass cap mkd.

$$\begin{array}{c|cccc}
 & T10N & R27E \\
 & S & 7 & S & 8
\end{array}$$

1968

deposit broken glass alongside the iron post and raise a mound of stone, 3 ft. base, 2 ft. high, W. of cor.

From this corner, the cor. of secs. 8 and 17, bears S. 1° 31' E., 3.97 chs. dist.

Land, mountainous.
Soil, sandy clay loam and rocky.
Undergrowth, shadscale, budsage and blackbrush.

## GENERAL DESCRIPTION

The area surveyed and resurveyed within Township 10 North Range 27 East, varies from mountainous in the west portion to nearly level in the central portion with the remaining terrain being gently rolling. The elevation ranges from about 4,700 to 5,600 ft. above sea level. The soil varies from sandy clay loam and rocky on the higher elevations to black loam on the bottom land. The vegetation consists of shadscale, blackbrush, budsage, sagebrush, meadow grass and other sparse native grasses. There are scattered stands of buckthorn, willow and cottonwood along the East Walker River which crosses the township in a northerly course.

The Rafter Seven ranch house is situated on the south boundary of sec. 33 and there are numerous buildings belonging to the Santa Margarita Ranch, in secs. 16 and 21. No mineral formations of consequence were noted during the survey.

Access into the area is provided by numerous trail roads. Principal users of the area are cattlemen.