

482

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES OF  
T. 1 S., R. 69 E.

## CHAINS

Land, rolling.  
Soil, sandy clay loam to rocky.  
Undergrowth, sagebrush.  
Timber, none.

The W.  $\frac{1}{4}$  sec. cor. of sec. 19, is on the E. bdy. of sec. 24, T. 1 S., R. 68 E., and on the E-W. center line of sec. 19.

At the corner point

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 13 ins. in the ground to solid rock and in a mound of stone, 5 ft. base to top, with brass cap mkd.

T1S  
| R69E  
|  $\frac{1}{4}$   
| S 19

1971

From this cor., the  $\frac{1}{4}$  sec. cor. of secs. 19 and 24, set in the 1902 survey, as described in the field notes of the concurrent resurvey of T. 1 S., R. 68 E., bears N.  $89^{\circ} 53' W.$ , 4.09 chs. dist.

From this same cor., the  $\frac{1}{4}$  sec. cor. of sec. 24, on the E. bdy. of T. 1 S., R. 68 E., monumented with an iron post,  $2\frac{1}{2}$  ins. diam., set, mkd. and witnessed as described in the field notes of the concurrent resurvey of T. 1 S., R. 68 E., bears N.  $0^{\circ} 12' E.$ , 2.05 chs. dist.

From this same cor., the  $\frac{1}{4}$  sec. cor. of secs. 19 and 20, bears S.  $89^{\circ} 53' E.$

## GENERAL DESCRIPTION

The land within this survey of Township 1 South, Range 69 East, is rolling to nearly level. The elevation ranges from about 4,500 to 5,000 ft. above sea level.

The soil ranges from sandy clay loam in the east portion to rocky in the west portion. The vegetation consists of sagebrush, and scattered juniper trees. The area drains in a northerly direction.

There is a graveled road running N. and S. through the area. Principal use of the area is grazing.