

DEPENDENT RESURVEY OF THE EIGHTH STANDARD PARALLEL NORTH,
THROUGH A PORTION OF RANGE 53 EAST

CHAINS	DEPENDENT RESURVEY OF THE EIGHTH STANDARD PARALLEL NORTH, THROUGH A PORTION OF RANGE 53 EAST
	<p>Reestablishment of a Portion of the Survey Executed by A.J. Hatch and J.H. Eaton, U.S. Deputy Surveyors, in 1870, Resurveyed by T.H. Lowe, U.S. Deputy Surveyor, in 1900, and Resurveyed by L.H. Taylor and W.A. Keddie, U.S. Deputy Surveyors, in 1905.</p> <hr/> <p>The standard $\frac{1}{4}$ sec. cor. of sec. 32, monumented with an unmarked quartzite stone, 20x8x6 ins., firmly set 10 ins. in the ground. This position is harmoniously related to existing marked corners and is accepted as the best available evidence of the position of the corner.</p> <p>At the corner point</p> <p>Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">S C T41N R53E <u>$\frac{1}{4}$ S 32</u></p> <p style="text-align: center;">1976</p> <p>bury the unmarked stone alongside the iron post.</p> <p>N. $89^{\circ} 20'$ W., along the S. bdy. of sec. 32.</p> <p>Over mountainous land, covered with sagebrush; desc. 90 ft. over a W. slope.</p> <p>2.50 Draw, drains SSW.</p> <p>4.80 Draw, drains SE.; asc. 360 ft. over an E. slope.</p> <p>16.00 Spur, slopes SE.; along a broken S. slope.</p> <p>29.00 Head of draw, drains SE.; asc. 100 ft. over an E. slope.</p> <p>34.46 The closing corner of secs. 5 and 6, T. 40 N., R. 53 E., monumented with a mound of stone. No marked stone found. This position is harmoniously related to existing marked corners and is accepted as the best available evidence of the position of the corner.</p> <p>At the corner point</p> <p>Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 16 ins. in the ground to bedrock and in a mound of stone, 3 ft. base to top, with brass cap mkd.</p>