

246

SURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,
TOWNSHIP 7 SOUTH, RANGE 70 EAST, MDM, NEVADA

CHAINS	
	<p>A pinon pine, 10 ins. diam., bears S. 65° E., 54 lks. dist., with S18 BT visible on open blaze.</p> <p>A juniper, 5 ins. diam., bears S. 52 1/2° W. 46 lks. dist., with S 13 BT visible on open blaze.</p> <p>A juniper, 12 ins. diam., bears N. 66 1/2° W., 21 lks. dist., with S12 BT visible on open blaze.</p> <p>N. 89° 59' W., bet. secs. 12 and 13.</p> <p>Over rocky mountainous land, through scattering timber and medium undergrowth.</p>
26.50	Ridge, bears N. and S.
39.95	Point for the 1/4 sec. cor. of secs. 12 and 13.
	<p>Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 12 ins. in the ground to solid rock and in a mound of stone, 3 ft. base to top, with brass cap mkd.</p> <p style="text-align: center;">T7S R70E 1/4 S 12 S 13</p> <p style="text-align: center;">1990</p> <p>The cor. is located on top of ledge, 10 ft. high.</p>
70.00	Ravine, drains S.
79.90	The cor. of secs. 11, 12, 13 and 14.
	<p>Land, mountainous. Soil, rocky clay. Timber, juniper; undergrowth, bitterbrush and Brigham tea.</p>
GENERAL DESCRIPTION	
	<p>The land surveyed in this township is broken mountainous land. The soil is a sandy clay covered with broken rock. The land is covered with desert grass, blackbrush, sage, cacti and scrub oak. There are medium to dense stands of juniper and pinon pine in the township. The area is used for grazing of cattle.</p> <p>There is an open pit mine in sections 13 and 24.</p>