## DEPENDENT RESURVEY OF THE EAST BOUNDARY, TOWNSHIP 35 NORTH, RANGE 33 EAST, MDM, NEVADA

	TOWNSHIP 35 NORTH, RANGE 33 EAST, MDM, NEVADA
CHAINS	
	T35N  R33E  S 1  T35N R34E S 7
	1988 Reset the decayed remains of the original wooden post and set a steel fence post, 5½ ft. long, alongside the stainless steel post.
	N. 0° 47' W., along the E. bdy. of sec. 1.
	Over nearly level land, covered with medium shadscale, scattered greasewood and native grass.
17.54	The closing corner of the southwest corner of sec. 6, T. 35 N., R. 34 E., monumented with a stainless steel post, 2½ ins. diam., firmly set, showing 4 ins. above ground, with brass cap mkd. as described in the field notes of T. 35 N., R. 34 E., executed concurrently under this same Group.
	From this corner, the N 1/4 sec. cor. of sec. 7, T. 35 N., R. 34 E., monumented with a stainless steel post, 2½ ins. diam., firmly set, showing 4 ins. above ground, with brass cap mkd. as described in the field notes of T. 35 N., R. 34 E., executed concurrently under this same Group, bears S. 88° 35′ W., 18.72 chs. dist.
19.60	Trail road, bears irregularly E. and W.
40.00	Enter sand hills covered with medium greasewood, sagebrush and native grass.
40.57	Point for the E ½ sec. cor. of sec. l, at proportionate distance; there is no remaining evidence of the original corner.
	Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
	T35N R33E R34E 1/4   S 1
	1988