

DEPENDENT RESURVEY OF THE THIRD STANDARD PARALLEL NORTH  
THROUGH A PORTION OF RANGE 19 EAST, MDM, NEVADA

CHAINS

Reestablishment of the Survey Executed by  
B. Ives, U.S. Deputy Surveyor,  
in 1861.

Beginning at the stan.  $\frac{1}{4}$  sec. cor. of sec. 36, monumented with a granite stone, 19 x 14 x 8 ins. (Record, 20 x 14 x 8 ins.), firmly set, projecting 6 ins. above an embedded mound of stone, 4 ft. diam., with the marks  $\frac{1}{4}$ , visible, plainly chiseled on N. face. Recovered a #5 rebar, with brass disk mkd. LS1350, on N. side of stone.

At the corner point

Set a stainless steel post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 20 ins. in the ground with a magnet at base, and in a mound of stone, 4 ft. base, to top, with brass cap mkd.

SC  
T16N R19E  
 $\frac{1}{4}$  S 36

1990

Deposit mkd. stone, horizontally, on N. side of stainless steel post.

Deposit rebar, horizontally, on S. side of stainless steel post.

Cor. is located in shallow ravine, drains N. 40° E.

N. 89°41'00" W., on the S. bdy. of sec. 36.

34.263 The closing cor. of secs. 1 and 2, T. 15 N., R. 19 E., hereinafter described in the field notes of the dependent resurvey of the subdivisional lines of T. 15 N., R. 19 E.

40.168 The stan. cor. of secs. 35 and 36, monumented with a galvanized iron pipe, 2 ins. diam., firmly set, projecting 4 ins. above ground, with galvanized iron cap mkd. as described in the field notes of the 1985-88 dependent resurvey of the S. bdy. of T. 16 N., R. 19 E., executed under Group No. 623.

At the corner point

Set a stainless steel post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground with a magnet at base, and in a mound of stone,  $2\frac{1}{2}$  ft. base, to top, with brass cap mkd.

S C  
T16N R19E  
S 35 | S 36

1990

Deposit iron pipe alongside the stainless steel post.

Cor. is located in subdivision area, 20 lks. S. of asphalt driveway, 50 lks. N. of cement driveway.