

215

DEPENDENT RESURVEY OF THE SOUTH BOUNDARY,
T. 22 N., R. 32 E., MOUNT DIABLO MERIDIAN, NEVADA

CHAINS

From this point,

The standard cor. of secs. 32 and 33, on the S. bdy. of T. 21 N., R. 32 E., monumented with the decayed remains of a wooden post, 1 in. square, 10 ins. long, with illegible scribe marks visible, loosely set in a mound of earth, bears S. 89°51.8' E., 160.944 chs. dist.

At the corner point

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, over a DEEP-1 magnetic marker, with brass cap mkd.

SC	
T21N	R32E
S 32	S 33

1992

Reset the original wooden post and set a steel fence post, 5½ ft. long, alongside the stainless steel post.

From this same point,

The standard ¼ sec. cor. of sec. 31, on the S. bdy. of T. 21 N., R. 31 E., monumented with a stainless steel post, 2½ ins. diam., firmly set and exposed 4 ins. above the ground, with brass cap mkd. as described in the field notes of T. 21 N., R. 31 E., executed concurrently under this same Group, bears N. 89°51.8' W., 442.596 chs. dist.

The control lines were fully retraced. Portions of the control lines were inundated by waters in the Carson Sink area, making searches for some evidence of intervening corners impracticable. No other corner evidence was found.

GENERAL DESCRIPTION

The area resurveyed within Township 22 North, Range 32 East, is situated on the Carson Sink. The elevation is about 3,900 ft. above sea level. The soil varies from sandy to alkali. The vegetation consists of greasewood. The township sets within the Stillwater Wildlife Management Area.

Access into the township is provided by numerous improved and unimproved roads. No mineral formations of consequence were noted during the survey.
