

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,
T. 15 S., R. 66 E., MOUNT DIABLO MERIDIAN, NEVADA

CHAINS	
	<p>T15S R66E 1/4 S 6 S 5 2015</p> <p>Bury the broken concrete cylinder alongside the stainless steel post.</p> <p>Corner is located 1 ft. south of a barbed wire fence, bears E. and W.</p> <hr/> <p>N. 0°04'30" W, beginning new measurement.</p>
8.34	Barbed wire fence, bears S. 60° E. and N. 60° W.
10.30	Dirt road, 30 lks. wide, bears SE. and NW.
19.899	Point for the N 1/16 sec. cor. of secs. 5 and 6.
	<p>Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 28 ins. in the ground, over a plastic-encased magnet, with brass cap mkd.</p> <p>N 1/16 S 6 S 5 2015</p>
19.974	A rebar, established by persons unknown, 5/8 ins. diam., firmly set, flush with the ground, with an aluminum cap mkd. illegibly. This position is not utilized in the course of this survey.
29.00	Ravine 20 lks. wide, bears N. and SW.
39.947	The sec. cor. of secs. 5, 6, 31 and 32.
	<hr/> <p>SUBDIVISION OF SECTION 5, T. 15 S., R. 66 E., MOUNT DIABLO MERIDIAN, NEVADA</p> <hr/> <p>From the 1/4 sec. cor. of secs. 5 and 8.</p> <p>N. 0°05'40" W, on the N-S center line of sec. 5.</p>
6.80	Left bank of the Muddy River, course E.
20.146	The C-S 1/16 sec. cor. of sec. 5, determined by Ernest H. Clary, Nevada Professional Land Surveyor No. 290, in 1963, monumented with a broken concrete cylinder, 6 ins. diam., 18 ins. long, buried 32 ins. below the surface of the ground, as recorded in Clark County, Nevada, File 12, Page 20, of Surveys. This is accepted as a careful and faithful determination of the position of the corner.