

SUBDIVISION OF SECTION 36,
T. 24 N., R. 23 E., MOUNT DIABLO MERIDIAN, NEVADA

CHAINS	
2.30	Toe of left bank of Mud Lake (Winnemucca Lake) slough, bears NE. and SW.
4.00	Enter sand dunes, thence across sand with little vegetation.
19.986	Point for the NW 1/16 sec. cor. of sec. 36, at intersection with the E-W center line of the NW1/4. Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 26 ins. in the ground, over a plastic-encased magnet, with brass cap mkd. NW 1/16 S36 2019
30.00	Leave sand dunes.
31.20	Toe of left bank of Mud Lake (Winnemucca Lake) slough, bears NE. and SW., thence across dry slough, course SW.
31.50	Toe of right bank of Mud Lake (Winnemucca Lake) slough, bears NE. and SW.
39.972	The point for the W 1/16 sec. cor. of secs. 25 and 36. <hr/>
	From the C-N 1/16 sec. cor. of sec. 36. N. 89°52'00" W., on the E-W center line of the NW1/4 of sec. 36.
1.00	Enter sand dunes, thence across sand with little vegetation.
19.981	The NW 1/16 sec. cor. of sec. 36.
39.962	The point for the N 1/16 sec. cor. of secs. 35 and 36. <hr/>
	GENERAL DESCRIPTION
	The average elevation of the area surveyed is approximately 4000 feet. General drainage is to the North. Vegetation consists of sagebrush and cheat grass. No trees remain since the original surveys and retracements. Tree stumps are all that remain. Soils consist mainly of sand with scattered tufa stone of various size. Mud Lake Slough is dry and no other water sources were encountered. <hr/>