DEPARTMENT OF THE INTERIOR

## UNITED STATES RECLAMATION SERVICE


A. P. DAVIS DIRECTOR AND CHIEF ENGINEER

TRUCKEE-CARSON PROJECT NEVADA SUPPLEMENTAL PLAT


SECTION 30

## TOWNSHIP 19 NORTH RANGE 30 EAST M. D. M. NEVADA

SURVEYED BY J. J. WALSH SURVEYOR U. S. R. S. UNDER DEPARTMENTAL INSTRUCTIONS OF OCTOBER 24, 1906 APRIL - MAY 1912 SCALE 4 INCHES = 1 MILE



- O DENOTES CORNER OF ORIGINAL SURVEY FOUND IN PLACE
- O DENOTES CORNER SET BY J. J. WALSH SURVEYOR, U. S. R. S.
- DENOTES WITNESS CORNER SET BY J. J. WALSH, SURVEYOR, U. S. R. S.



THE ACCOMPANYING DIAGRAM OF THE SURVEY OF SECTION 30 IN T. 19 N., R. 30 E., M. D. M., NEVADA, EXECUTED UNDER AUTHORITY OF DEPARTMENTAL INSTRUCTIONS OF OCTOBER 24, 1906, IS CORRECT AND ACCORDING TO

FILE IN THIS OFFICE, WHICH HAVE BEEN EXAMINED IN ACCEPTED. THE FIELD NOTES THEREOF ON FILE IN THIS OFFICE, WHICH HAVE BEEN EXAMINED AND APPROVED.

U. S. RECLAMATION SERVICE

DIRECTOR AND CHIEF ENGINEER

March 16, 1915

g.cm.

THE ACCOMPANYING DIAGRAM OF THE SURVEY OF SECTION 30 IN T. 19 N.,

TMENT OF THE INTE

ACCESSION NO. 16056